

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION VII 901 NORTH 5TH STREET KANSAS CITY, KANSAS 66101

April 19, 2001

North Star Steel Jack Skelley P.O. Box 749 Wilton, IA 52778

Re:

Transmittal of Analytical Results

North Star Steel

RCRA ID#000223354

Dear Mr. Skelley:

Enclosed you will find copies of the analytical results from the soil and waste samples that were collected February 21-23, 2001, at the above-referenced facility on by the U.S. Environmental Protection Agency.

If you have any questions regarding this information, please contact me at (913) 551-7049.

Sincerely,

Dedriel Newsome

Environmental Engineer

Dehorah Cade

Air and RCRA Compliance Branch

Environmental Services Division

Enclosure

cc: Iowa Department of Natural Resources

R00184416

RCRA RECORDS CENTER



United States Environmental Protection Agency

Region 7 Laboratory 25 Funston Road Kansas City, KS 66115

Date: 3/21/2001

Subject: Transmittal of Sample Analysis Results for ASR #: 902

Activity Number: DLN16

Activity Description: North Star Steel

From: Michael Thomas, Associate Laboratory Director

Regional Laboratory, Environmental Services Division

To: Dedriel Newsome

ENSV/ARCM

This is the sample analysis results transmittal for the above-referenced Analytical Services Request (ASR). The data contained in this transmittal have been approved by the Regional Laboratory. This transmittal contains all of the sample analysis results for this ASR. The Regional Laboratory should be notified within 14 days if any changes are needed to the contents of this report. If you have any questions, comments or data changes, please contact the Laboratory Customer Service Department at 913-551-5295.

cc: Analytical Data File

ASR Number: 902

Summary of Activity Information

3/21/2001

Activity Leader: Newsome, Dedriel

Org: ENSV/ARCM

Phone: (913) 551-7049

Activity Number: DLN16

Activity Desc: North Star Steel

Location: Wilton

State: lowa

Type: RCRA

Purpose: Compliance monitoring

Explanation of Codes, Units and Qualifiers used on this report.

Sample QC Codes: QC Codes identify the type of

Units: Specific units in which results are reported.

sample for quality control

%

= Percent

= Field Sample

mg/kg

= Milligrams per Kilogram

= Field Duplicate FD

mg/L

= Milligrams per Liter

Data Qualifiers: Specific codes used in conjunction with data values to provide additional information on the quality of reported results, or used to explain the absence of a specific value.

(Blank) = Values have been reviewed and found acceptable for use.

U = Not detected at or above the reportable level shown.

Activity Desc: North Star Steel

ASR Number: 902

Sample Information Summary

3/21/2001

Sample QC Numbe Code	Matrix	Location	External Sample No.	Start Date	Start Time	End Date	End Time	Receipt Date
1	Soil	South side overhead door, EAF dust lead-out bldg. grab sample (0-1 to 2" below gravel)	2	02/22/2001	9:45	02/22/2001	10:00	02/26/2001
1 - FD	Soil	South side overhead door, EAF dust lead-out bldg. grab sample (0-1 to 2" below gravel)/Duplicate of sample 1		02/22/2001	9:45	02/22/2001	10:00	02/26/2001
2	Soil	North side of overhead door, EAF dust lead-out bldg. grab sample (0-1 to 2" below gravel)		02/22/2001	10:05	02/22/2001	10:20	02/26/2001
3	Soil	Outside Southeast door of new baghouse bldg./gravel collected 2-6" from surface		02/22/2001	10:30	02/22/2001	10:40	02/26/2001
4	Soil	Slag from intermediate slag set- down area, West of melt shop (about 2' off the ground)		02/22/2001	10:55	02/22/2001	11:10	02/26/2001
5	Soil	Soil outside Southeast overhead door of old pelletizer bldg. (soil sample 0-1.5" depth)		02/22/2001	11:20	02/22/2001	11:40	
6	Soil	Soil West of old baghouse bldg. (0-1.5" soil)		02/22/2001	11:45	02/22/2001	12:00	02/26/2001
7	Soil	Fine dirt from Northwest corner outside old baghouse bldg. (0-1.5" soil)		02/22/2001	12:00	02/22/2001	12:15	
8	Soil	Rail car clean out dirt soil sample		02/22/2001	14:50	02/22/2001	14:55	02/26/2001
9	Soil	Background soil sample from ditch off county gravel Rd. 1/2 mile Northwest of NNS facility		02/22/2001	15:45	02/22/2001	16:00	02/26/2001

Activity Desc: North Star Steel

16 ASR Number: 902

RLAB Approved Analysis Comments

3/21/2001

Analysis

Comments About Results For This Analysis

Total Metals Analysis of TCLP Metals in Soil by ICAP

Low matrix spike/matrix spike duplicate recoveries, caused by matrix interference, may indicate a low

bias in the sample results.

The laboratory control samples were in control.

Selenium

Silver

Activity Desc: North Star Steel

ASR Number: 902

mg/kg

mg/kg

RLAB Approved Sample Analysis Results

10.0 U

2.00 U

10.0 U

5.44

3/21/2001

10.0 U

2.00 U

Analysis / Analyte	Units	Units 1		1-FD		2	3			
Percent Solid										
Solids, percent	%	94.2		94.6		89.1		97.7		
TCLP Metals in Soil										
Arsenic	mg/L	0.0500	U	0.0500	U	0.0514		0.0500	U	
Barium	mg/L	1.20		1.21		0.625		0.200	U	
Cadmium	mg/L	0.00500	U	0.00500	U	0.00500	U	0.00500	U	
Chromium	mg/L	0.0100	U	0.0117		0.0100	U	0.0100	U	
Lead	mg/L	0.0500	U	0.0500	U	0.0500	U	0.0500	U	
Selenium	mg/L	0.0500	U	0.0500	U	0.0500	U	0.0500	U	
Silver	mg/L	0.0100	U	0.0100	U	0.0100	U	0.0100	U	
Total Metals Analysis of TCLP Me	etals in Soil by ICAP									
Arsenic	mg/kg	5.00	U	5.00	U	5.00	U	5.00	U	
Barium	mg/kg	308		309		70.2		2.85	1	
Cadmium	mg/kg	24.1		24.2		4.29		1,00	U	
Chromium	mg/kg	898		931		193		2.00	U	
Lead	mg/kg	31.5		26.5		23.8		5.00	U	

10.0 U

6.17

Silver

Activity Desc: North Star Steel

ASR Number: 902

mg/kg

RLAB Approved Sample Analysis Results

3/21/2001

Analysis / Analyte	Units	4		5		6		7	
Percent Solid									
Solids, percent	%	99.9		84.5		88.5		54.7	
TCLP Metals in Soil									
Arsenic	mg/L	0.0500	U	0.0500	U	0.0500	U	0.0500	U
Barium	mg/L	0.726		1.17		1.28		0.783	
Cadmium	mg/L	0.00500	U	0.0889		0.256		0.257	
Chromium	mg/L	0.0100	U	0.0100	U	0.0100	U	0.0117	
Lead	mg/L	0.0500	U	0.0500	U	0.183		0.0500	U
Selenium	mg/L	0.0500	U	0.0500	U	0.0500	U	0.0500	U
Silver	mg/L	0.0100	U	0.0100	U	0.0100	U	0.0100	U
Total Metals Analysis of TCLP M	etals in Soil by ICAP								
Arsenic	mg/kg	5.00	U	5.00	U	5.00	U	5.00	U
Barium	mg/kg	197		200		189		211	
Cadmium	mg/kg	24.6		40.7		42.6		63.2	
Chromium	mg/kg	654		571		653		765	
Lead	mg/kg	26.6		403		805		1670	
Selenium	mg/kg	10.0	U	10.0	U	10.0	U	10.0	U
Silver	mg/kg	2.71		5.45		6.17		8.69	

Activity Desc: North Star Steel

ASR Number: 902

RLAB Approved Sample Analysis Results

3/21/2001

Analysis / Analyte	Units	8		9	· ·			
Percent Solid							×	
Solids, percent	%	88.0		54.6		25		
TCLP Metals in Soil								
Arsenic	mg/L	0.0500	U	0.0500	U			
Barium	mg/L	1.05		0.487				
Cadmium	mg/L	0.0678		0.00500	U			
Chromium	mg/L	0.0100	U	0.0100	U			
Lead	mg/L	0.0500	U	0.0500	U			
Selenium	mg/L	0.0500	U	0.0500	U			
Silver	mg/L	0.0100	U	0.0100	U			
Total Metals Analysis of TCLP Metals in S	oil by ICAP							
Arsenic	mg/kg	5.00	U	5.00	U			
Barium	mg/kg	298		112				
Cadmium	mg/kg	39.3		1.19				
Chromium	mg/kg	584		15.6			18	
Lead	mg/kg	538		16.5				
Selenium	mg/kg	10.0	U	10.0	U			
Silver	mg/kg	3.01		2.00	U			